

## TEST CERTIFICATE

No. : C12 / 43570

Client

**S Lilley & Son Ltd**  
80 Alcester Street  
Birmingham  
B12 0QE U.K.

Client Contact

Mr. S J Lilley

Item/s tested

Glazed Ceramic Edison Screw E27 Lampholder  
250V, 4A, T270 for building in (surface mounting  
on 42.5mm centres) with screw terminals.  
Model : **SL5022**

Specification(s) to which above  
unit/s have been tested and  
compliance confirmed

All relevant clauses of **BS EN 60238:2004+A2 : 2011**  
and deemed to comply

Date of Issue

29<sup>th</sup> February 2012

Signed



*Rajeev Vagdia*  
( Certifying Officer )

Relating to Project File(s) held at  
Nemko Ltd

43570, 41302, 38369, N38977

To be read in conjunction  
with page 2 attached

Form No: QF102-1  
Issue No: 3  
Issue Date: 21.07.11



<b>Certificate No:</b>	<b>C12/ 43570</b>
<b>Client:</b>	<b>S Lilley &amp; Son Ltd.</b>

THIS CERTIFICATE APPLIES ONLY TO THE PARTICULAR SAMPLE UNIT(S) TESTED AND TO THE SPECIFIC TESTS CARRIED OUT AS DETAILED IN THE PROJECT FILE HELD AT NEMKO LTD.

THIS TEST CERTIFICATE DOES NOT COVER ELECTROMAGNETIC COMPATIBILITY.

IT SHOULD BE NOTED THAT ONLY A LIMITED NUMBER OF UNITS HAVE BEEN TESTED. IT IS THEREFORE ESSENTIAL FOR THE MANUFACTURER OR SUPPLIER OF THIS PRODUCT TO ENSURE THAT THE QUALITY OF ALL PRODUCTION UNITS IS OF THE SAME STANDARD AS THAT OF THE SAMPLE(S) CHECKED

WHERE FULL TESTING OF APPROVED COMPONENTS HAS NOT BEEN CARRIED OUT AS PART OF THIS REPORT, IT IS THE RESPONSIBILITY OF THE MANUFACTURER OR SUPPLIER TO ENSURE THE COMPONENTS USED IN PRODUCTION UNITS ARE AS THAT OF THE RELATED CERTIFICATES AND SUPPORTING DOCUMENTATION.

Condition / number of test sample : Good /10 **Serial Number(s) :-** N/A

**Notes relating to this certificate :-** Australia & New Zealand differences according to AS/NZS 60238 have also been assessed

**Project History: -**

<u>Job Number</u>	<u>Sample received</u>	<u>Job Completion Date</u>	<u>Summary of work carried out</u>
43570	30-Jan-12	29-Feb-12	Report update and the addition of Australia & New Zealand differences
41302	15-April-10	13-May-10	Update inspection
38369	22-Aug-07	29-Aug-07	Update inspection
N38977	08-Feb-05	14-Mar-05	Full Test

\*\*\*\*\* **END OF CERTIFICATE** \*\*\*\*\*

